

Crash Date	Crash Severity	Time	Light Conditions	Manner of Collision	Road Surface Condition	Traffic Control Device Type	Vehicle Actions Prior to Crash (All Vehicles)	Latitude	Longitude
02/05/2016	PDO	11:20 AM	Daylight	Sideswipe, same direction	Snow	No controls	V1: Travelling straight ahead / V2: Parked	42.47343107	-70.89454801
03/16/2016	PDO	6:40 PM	Dusk	Rear-end	Dry	Yield signs	V1: Travelling straight ahead / V2: Slowing or stopped in traffic	42.47112654	-70.89458226
06/24/2016	PDO	12:10 PM	Daylight	Rear-end	Dry	Yield signs	V1: Entering traffic lane / V2: Slowing or stopped in traffic	42.47075745	-70.89458588
05/26/2016	Not Reported	6:00 AM	Daylight	Sideswipe, same direction	Dry	Not reported	V1: Slowing or stopped in traffic / V2: Slowing or stopped in traffic	42.47112654	-70.89458226
05/26/2016	Non-fatal injury	2:14 PM	Daylight	Single vehicle crash	Dry	No controls	V1: Travelling straight ahead	42.46972071	-70.89603066
06/23/2016	PDO	5:33 PM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Slowing or stopped in traffic	42.47112654	-70.89458226
08/21/2016	Not Reported	10:59 PM	Dark - lighted roadway	Single vehicle crash	Not reported	No controls	V1: Turning left	42.47112654	-70.89458226
09/02/2016	Non-fatal injury	6:15 AM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Travelling straight ahead	42.47112654	-70.89458226
09/07/2016	PDO	8:42 AM	Daylight	Rear-end	Wet	Traffic control signal	V1: Travelling straight ahead / V2: Slowing or stopped in traffic	42.47112654	-70.89458226
12/10/2016	PDO	6:24 PM	Dark - lighted roadway	Angle	Dry	No controls	V1: Making U-turn / V2: Travelling straight ahead	42.47116836	-70.89397383
05/18/2017	Non-fatal injury	3:46 PM	Daylight	Single vehicle crash	Dry	No controls	V1: Travelling straight ahead	42.47265345	-70.89219625
06/12/2017	PDO	4:25 PM	Daylight	Angle	Dry	No controls	V1: Travelling straight ahead / V2: Turning left	42.47112654	-70.89458226
09/09/2017	PDO	9:35 AM	Daylight	Angle	Dry	Stop signs	V1: Travelling straight ahead / V2: Turning left	42.47388891	-70.89430039
12/10/2017	PDO	2:14 AM	Dark - lighted roadway	Single vehicle crash	Snow	No controls	V1: Travelling straight ahead	42.47391579	-70.89427581
10/07/2017	PDO	9:36 AM	Dark - lighted roadway	Angle	Dry	No controls	V1: Parked / V2: Backing	42.47290829	-70.8961461
10/19/2017	PDO	7:18 AM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Travelling straight ahead	42.47070337	-70.89457416
11/03/2017	Non-fatal injury	4:03 PM	Daylight	Head-on	Wet	No controls	V1: Travelling straight ahead / V2: Entering traffic lane / V3: Slowing or stopped in traffic	42.47388891	-70.89430039
02/09/2018	PDO	7:43 AM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Travelling straight ahead	42.47070397	-70.89458005
07/08/2018	PDO	2:24 PM	Daylight	Rear-end	Dry	Yield signs	V1: Entering traffic lane / V2: Slowing or stopped in traffic	42.47070397	-70.89458005
06/10/2018	Non-fatal injury	7:37 AM	Daylight	Angle	Dry	No controls	V1: Turning left	42.47070397	-70.89458005
10/10/2018	PDO	5:36 PM	Daylight	Rear-end	Dry	No controls	V1: Travelling straight ahead / V2: Travelling straight ahead	42.47070397	-70.89458005
12/18/2018	PDO	9:59 AM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Travelling straight ahead	42.47070397	-70.89458005
12/09/2018	Non-fatal injury	11:36 AM	Daylight	Rear-end	Dry	No controls	V1: Travelling straight ahead / V2: Slowing or stopped in traffic / V3: Slowing or stopped in traffic	42.47015649	-70.8953305
03/14/2019	PDO	6:19 PM	Daylight	Rear-end	Dry	Yield signs	V1: Travelling straight ahead / V2: Slowing or stopped in traffic	42.47070397	-70.89458005
05/13/2019	Non-fatal injury	5:24 PM	Daylight	Angle	Wet	No controls	V1: Travelling straight ahead / V2: Turning left	42.47070397	-70.89458005
07/26/2019	PDO	11:29 AM	Daylight	Rear-end	Dry	Traffic control signal	V1: Travelling straight ahead / V2: Travelling straight ahead	42.47070397	-70.89458005
08/31/2019	PDO	9:05 AM	Daylight	Rear-end	Dry	Yield signs	V1: Travelling straight ahead / V2: Slowing or stopped in traffic	42.47070397	-70.89458005
10/28/2019	PDO	7:11 PM	Dark - lighted roadway	Rear-end	Wet	Stop signs	V1: Travelling straight ahead / V2: Slowing or stopped in traffic	42.47388888	-70.89429508
11/05/2019	Non-fatal injury	12:31 AM	Dark - lighted roadway	Sideswipe, same direction	Dry	No controls	V1: Parked / V2: Travelling straight ahead	42.47400078	-70.89819584
11/15/2019	PDO	4:15 PM	Daylight	Rear-end	Dry	Yield signs	V1: Slowing or stopped in traffic / V2: Travelling straight ahead	42.47070397	-70.89458005
01/19/2020	PDO	2:59 AM	Dark - lighted roadway	Single vehicle crash	Snow	Unknown	V1: Travelling straight ahead	42.47317125	-70.89460248
11/26/2020	PDO	1:41 AM	Dark - lighted roadway	Sideswipe, opposite direction	Dry	No controls	V1: Parked / V2: Turning right	42.47290423	-70.896395
08/10/2020	PDO	9:17 AM	Daylight	Angle	Dry	No controls	V1: Travelling straight ahead / V2: Turning left	42.47015648	-70.8953305